

**Ambient Monitoring Data in the Plant :-**

Conc of PM 2.5:-

Date	Location	( $\mu\text{g}/\text{m}^3$ )	Date	Location	( $\mu\text{g}/\text{m}^3$ )	Date	Location	( $\mu\text{g}/\text{m}^3$ )
01/04/16	Nr Contractor Room	36.60	02/04/16	Nr Rail Gate	27.27	04/04/16	Nr Water Tank	28.93
05/04/16	Nr Contractor Room	33.87	06/04/16	Nr Rail Gate	28.95	07/04/16	Nr Water Tank	30.34
08/04/16	Nr Contractor Room	35.60	09/04/16	Nr Rail Gate	29.61	11/04/16	Nr Water Tank	34.38
12/04/16	Nr Contractor Room	38.05	13/04/16	Nr Rail Gate	37.74	14/04/16	Nr Water Tank	35.37
15/04/16	Nr Contractor Room	31.60	16/04/16	Nr Rail Gate	34.43	18/04/16	Nr Water Tank	37.67
19/04/16	Nr Contractor Room	29.51	20/04/16	Nr Rail Gate	33.02	21/04/16	Nr Water Tank	34.23
22/04/16	Nr Contractor Room	33.30	23/04/16	Nr Rail Gate	31.99	25/04/16	Nr Water Tank	32.20
26/04/16	Nr Contractor Room	37.20	27/04/16	Nr Rail Gate	33.34	28/04/16	Nr Water Tank	32.73
29/04/16	Nr Contractor Room	44.55	30/04/16	Nr Rail Gate	41.90	02/05/16	Nr Water Tank	39.66
03/05/16	Nr Contractor Room	42.23	04/05/16	Nr Rail Gate	45.25	05/05/16	Nr Water Tank	43.80
06/05/16	Nr Contractor Room	41.26	07/05/16	Nr Rail Gate	39.61	09/05/16	Nr Water Tank	40.19
10/05/16	Nr Contractor Room	46.16	11/05/16	Nr Rail Gate	43.73	12/05/16	Nr Water Tank	49.35
13/05/16	Nr Contractor Room	38.81	14/05/16	Nr Rail Gate	45.81	16/05/16	Nr Water Tank	46.98
17/05/16	Nr Contractor Room	45.70	18/05/16	Nr Rail Gate	44.34	19/05/16	Nr Water Tank	27.61
20/05/16	Nr Contractor Room	29.51	21/05/16	Nr Rail Gate	31.19	23/05/16	Nr Water Tank	35.02
24/05/16	Nr Contractor Room	27.35	25/05/16	Nr Rail Gate	26.87	26/05/16	Nr Water Tank	30.63
27/05/16	Nr Contractor Room	32.17	28/05/16	Nr Rail Gate	33.73	30/05/16	Nr Water Tank	33.37
31/05/16	Nr Contractor Room	31.32	01/06/16	Nr Rail Gate	38.14	02/06/16	Nr Water Tank	35.30
03/06/16	Nr Contractor Room	27.16	04/06/16	Nr Rail Gate	23.78	06/06/16	Nr Water Tank	26.83
07/06/16	Nr Contractor Room	24.36	08/06/16	Nr Rail Gate	24.12	09/06/16	Nr Water Tank	25.58
10/06/16	Nr Contractor Room	26.17	11/06/16	Nr Rail Gate	25.49	13/06/16	Nr Water Tank	25.93
14/06/16	Nr Contractor Room	26.03	15/06/16	Nr Rail Gate	25.93	16/06/16	Nr Water Tank	28.40
17/06/16	Nr Contractor Room	25.28	18/06/16	Nr Rail Gate	25.09	20/06/16	Nr Water Tank	25.74
21/06/16	Nr Contractor Room	26.86	22/06/16	Nr Rail Gate	27.29	23/06/16	Nr Water Tank	24.20
24/06/16	Nr Contractor Room	25.49	25/06/16	Nr Rail Gate	25.49	27/06/16	Nr Water Tank	27.65
28/06/16	Nr Contractor Room	24.33	29/06/16	Nr Rail Gate	26.25	30/06/16	Nr Water Tank	26.28



*Alaka*

Cont. of PM 2.S :-

Annexure - II

01/07/16	Nr Contractor Room	18.75	02/07/16	Nr Rail Gate	18.78	04/07/16	Nr CCR	20.74
05/07/16	Nr Contractor Room	20.18	06/07/16	Nr Rail Gate	17.58	07/07/16	Nr CCR	20.18
08/07/16	Nr Contractor Room	18.36	09/07/16	Nr Rail Gate	19.57	11/07/16	Nr CCR	19.52
12/07/16	Nr Contractor Room	17.72	13/07/16	Nr Rail Gate	20.32	14/07/16	Nr CCR	17.34
15/07/16	Nr Contractor Room	20.31	16/07/16	Nr Rail Gate	34.10	18/07/16	Nr CCR	38.80
19/07/16	Nr Contractor Room	34.89	20/07/16	Nr Rail Gate	30.61	21/07/16	Nr CCR	35.30
22/07/16	Nr Contractor Room	45.90	23/07/16	Nr Rail Gate	31.58	25/07/16	Nr CCR	47.44
26/07/16	Nr Contractor Room	44.97	27/07/16	Nr Rail Gate	26.87	28/07/16	Nr CCR	37.80
29/07/16	Nr Contractor Room	53.64	30/07/16	Nr Rail Gate	19.20	01/08/16	Nr CCR	38.69
02/08/16	Nr Contractor Room	52.13	03/08/16	Nr Rail Gate	18.56	04/08/16	Nr CCR	34.43
05/08/16	Nr Contractor Room	41.94	06/08/16	Nr Rail Gate	22.45	08/08/16	Nr CCR	26.83
09/08/16	Nr Contractor Room	39.65	10/08/16	Nr Rail Gate	26.41	11/08/16	Nr CCR	40.25
12/08/16	Nr Contractor Room	44.97	13/08/16	Nr Rail Gate	44.33	16/08/16	Nr CCR	53.67
17/08/16	Nr Contractor Room	49.78	18/08/16	Nr Rail Gate	26.84	19/08/16	Nr CCR	41.86
20/08/16	Nr Contractor Room	47.05	22/08/16	Nr Rail Gate	18.16	23/08/16	Nr CCR	39.91
24/08/16	Nr Contractor Room	29.70	25/08/16	Nr Rail Gate	28.75	26/08/16	Nr CCR	33.71
27/08/16	Nr Contractor Room	29.71	29/08/16	Nr Rail Gate	25.83	30/08/16	Nr CCR	29.70
31/08/16	Nr Contractor Room	33.41	01/09/16	Nr Rail Gate	29.22	02/09/16	Nr CCR	26.87
03/09/16	Nr Contractor Room	33.10	05/09/16	Nr Rail Gate	30.71	06/09/16	Nr CCR	27.36
07/09/16	Nr Contractor Room	27.19	08/09/16	Nr Rail Gate	27.87	09/09/16	Nr CCR	23.90
10/09/16	Nr Contractor Room	26.86	12/09/16	Nr Rail Gate	23.49	13/09/16	Nr CCR	30.35
14/09/16	Nr Contractor Room	30.45	15/09/16	Nr Rail Gate	26.17	16/09/16	Nr CCR	26.86
17/09/16	Nr Contractor Room	28.04	19/09/16	Nr Rail Gate	27.11	20/09/16	Nr CCR	25.95
21/09/16	Nr Contractor Room	26.13	22/09/16	Nr Rail Gate	34.07	23/09/16	Nr CCR	23.81
24/09/16	Nr Contractor Room	27.87	26/09/16	Nr Rail Gate	22.05	27/09/16	Nr CCR	27.42
28/09/16	Nr Contractor Room	32.03	29/09/16	Nr Rail Gate	31.16	30/09/16	Nr CCR	25.50



## Conc of PM 10:-

Date	Location	( $\mu\text{g}/\text{m}^3$ )	Date	Location	( $\mu\text{g}/\text{m}^3$ )	Date	Location	( $\mu\text{g}/\text{m}^3$ )
01/04/2016	Nr Contractor Room	61.52	02/04/2016	Nr Rail Gate	63.18	04/04/2016	Nr Water Tank	54.53
05/04/2016	Nr Contractor Room	67.03	06/04/2016	Nr Rail Gate	63.86	07/04/2016	Nr Water Tank	57.27
08/04/2016	Nr Contractor Room	57.84	09/04/2016	Nr Rail Gate	56.54	11/04/2016	Nr Water Tank	46.98
12/04/2016	Nr Contractor Room	41.25	13/04/2016	Nr Rail Gate	51.30	14/04/2016	Nr Water Tank	59.76
15/04/2016	Nr Contractor Room	51.20	16/04/2016	Nr Rail Gate	71.11	18/04/2016	Nr Water Tank	56.48
19/04/2016	Nr Contractor Room	49.62	20/04/2016	Nr Rail Gate	69.16	21/04/2016	Nr Water Tank	47.02
22/04/2016	Nr Contractor Room	50.42	23/04/2016	Nr Rail Gate	71.04	25/04/2016	Nr Water Tank	52.97
26/04/2016	Nr Contractor Room	57.66	27/04/2016	Nr Rail Gate	76.96	28/04/2016	Nr Water Tank	48.93
29/04/2016	Nr Contractor Room	68.96	30/04/2016	Nr Rail Gate	64.63	02/05/2016	Nr Water Tank	51.35
03/05/2016	Nr Contractor Room	64.63	04/05/2016	Nr Rail Gate	60.93	05/05/2016	Nr Water Tank	65.95
06/05/2016	Nr Contractor Room	62.81	07/05/2016	Nr Rail Gate	77.11	09/05/2016	Nr Water Tank	62.81
10/05/2016	Nr Contractor Room	66.81	11/05/2016	Nr Rail Gate	67.50	12/05/2016	Nr Water Tank	70.35
13/05/2016	Nr Contractor Room	75.32	14/05/2016	Nr Rail Gate	70.07	16/05/2016	Nr Water Tank	86.16
17/05/2016	Nr Contractor Room	76.95	18/05/2016	Nr Rail Gate	63.81	19/05/2016	Nr Water Tank	71.18
20/05/2016	Nr Contractor Room	66.12	21/05/2016	Nr Rail Gate	61.25	23/05/2016	Nr Water Tank	73.90
24/05/2016	Nr Contractor Room	62.44	25/05/2016	Nr Rail Gate	70.48	26/05/2016	Nr Water Tank	60.30
27/05/2016	Nr Contractor Room	65.00	28/05/2016	Nr Rail Gate	64.94	30/05/2016	Nr Water Tank	57.95
31/05/2016	Nr Contractor Room	63.19	01/06/2016	Nr Rail Gate	73.13	02/06/2016	Nr Water Tank	63.44
03/06/2016	Nr Contractor Room	47.50	04/06/2016	Nr Rail Gate	61.01	06/06/2016	Nr Water Tank	67.70
07/06/2016	Nr Contractor Room	50.47	08/06/2016	Nr Rail Gate	58.63	09/06/2016	Nr Water Tank	51.77
10/06/2016	Nr Contractor Room	60.87	11/06/2016	Nr Rail Gate	58.75	13/06/2016	Nr Water Tank	63.00
14/06/2016	Nr Contractor Room	50.57	15/06/2016	Nr Rail Gate	64.18	16/06/2016	Nr Water Tank	50.83
17/06/2016	Nr Contractor Room	51.51	18/06/2016	Nr Rail Gate	64.01	20/06/2016	Nr Water Tank	51.93
21/06/2016	Nr Contractor Room	44.42	22/06/2016	Nr Rail Gate	56.25	23/06/2016	Nr Water Tank	56.03
24/06/2016	Nr Contractor Room	58.69	25/06/2016	Nr Rail Gate	52.55	27/06/2016	Nr Water Tank	68.96
28/06/2016	Nr Contractor Room	58.13	29/06/2016	Nr Rail Gate	53.64	30/06/2016	Nr Water Tank	53.70




*Alakar*

Cont. of PM 10 :-

Annexure - II

01/07/2016	Nr Contractor Room	53.61	02/07/2016	Nr Rail Gate	31.22	04/07/2016	Nr CCR	40.71
05/07/2016	Nr Contractor Room	36.58	06/07/2016	Nr Rail Gate	58.18	07/07/2016	Nr CCR	52.45
08/07/2016	Nr Contractor Room	46.10	09/07/2016	Nr Rail Gate	32.89	11/07/2016	Nr CCR	49.52
12/07/2016	Nr Contractor Room	59.00	13/07/2016	Nr Rail Gate	58.28	14/07/2016	Nr CCR	43.21
15/07/2016	Nr Contractor Room	55.18	16/07/2016	Nr Rail Gate	39.33	18/07/2016	Nr CCR	42.71
19/07/2016	Nr Contractor Room	36.26	20/07/2016	Nr Rail Gate	34.72	21/07/2016	Nr CCR	42.08
22/07/2016	Nr Contractor Room	37.44	23/07/2016	Nr Rail Gate	46.74	25/07/2016	Nr CCR	45.23
26/07/2016	Nr Contractor Room	31.34	27/07/2016	Nr Rail Gate	60.04	28/07/2016	Nr CCR	55.57
29/07/2016	Nr Contractor Room	61.20	30/07/2016	Nr Rail Gate	49.75	01/08/2016	Nr CCR	43.97
02/08/2016	Nr Contractor Room	49.50	03/08/2016	Nr Rail Gate	46.88	04/08/2016	Nr CCR	60.87
05/08/2016	Nr Contractor Room	49.55	06/08/2016	Nr Rail Gate	43.49	08/08/2016	Nr CCR	45.35
09/08/2016	Nr Contractor Room	39.30	10/08/2016	Nr Rail Gate	50.63	11/08/2016	Nr CCR	38.99
12/08/2016	Nr Contractor Room	48.08	13/08/2016	Nr Rail Gate	48.75	16/08/2016	Nr CCR	59.26
17/08/2016	Nr Contractor Room	45.09	18/08/2016	Nr Rail Gate	43.43	19/08/2016	Nr CCR	70.13
20/08/2016	Nr Contractor Room	52.76	22/08/2016	Nr Rail Gate	57.79	23/08/2016	Nr CCR	62.19
24/08/2016	Nr Contractor Room	49.52	25/08/2016	Nr Rail Gate	58.42	26/08/2016	Nr CCR	64.37
27/08/2016	Nr Contractor Room	52.34	29/08/2016	Nr Rail Gate	55.85	30/08/2016	Nr CCR	55.40
31/08/2016	Nr Contractor Room	65.49	01/09/2016	Nr Rail Gate	62.81	02/09/2016	Nr CCR	50.63
03/09/2016	Nr Contractor Room	64.44	05/09/2016	Nr Rail Gate	68.75	06/09/2016	Nr CCR	65.33
07/09/2016	Nr Contractor Room	70.98	08/09/2016	Nr Rail Gate	65.13	09/09/2016	Nr CCR	72.24
10/09/2016	Nr Contractor Room	74.75	12/09/2016	Nr Rail Gate	72.65	13/09/2016	Nr CCR	62.69
14/09/2016	Nr Contractor Room	61.56	15/09/2016	Nr Rail Gate	63.94	16/09/2016	Nr CCR	69.79
17/09/2016	Nr Contractor Room	83.04	19/09/2016	Nr Rail Gate	87.59	20/09/2016	Nr CCR	80.32
21/09/2016	Nr Contractor Room	63.75	22/09/2016	Nr Rail Gate	74.08	23/09/2016	Nr CCR	68.48
24/09/2016	Nr Contractor Room	70.07	26/09/2016	Nr Rail Gate	61.31	27/09/2016	Nr CCR	58.75
28/09/2016	Nr Contractor Room	61.07	29/09/2016	Nr Rail Gate	70.84	30/09/2016	Nr CCR	51.98



*Alaka*